

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/30/2024

Submitted Date:

10/08/2024

Document Number:

708201669**FIELD INSPECTION FORM**Loc ID 312228 Inspector Name: Edwardson, Dylan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 95620Name of Operator: WESTERN OPERATING COMPANYAddress: 1165 DELAWARE STREET #200City: DENVER State: CO Zip: 80204**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments3 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Heibel, Krystal		krystal.heibel@state.co.us	
JAMES, STEVEN		steve@westernoperating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219731	WELL	PR	11/01/2018	OW	075-06955	PROPST C-1X	RI
312228	LOCATION	AC			-	PROPST-611N53W 35NWNW	RI

General Comment:

This is a follow-up Interim Reclamation and Stormwater Inspection for Location ID (312228) and to the previous FIR (doc #708200709) conducted on 11/27/2023.

Refer to Environmental FIR (doc #709100423) conducted on 09/30/2024 for additional information.

Refer to the photo-documentation of the observed compliance issues attached to this report. Any corrective action(s) and corrective action due dates from previous inspections that have not been addressed are still applicable.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Previous FIR (doc #708200709) documented that there was no NFPA Placard at day tank next to wellhead. It does not appear that this corrective action has been addressed.		
Corrective Action:	Install sign to comply with Rule 605.h. (Original CA Date: 11/27/2023).	Date:	11/27/2023

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Previous FIR (doc #708200709) documented a metal pipe within an adjacent drainage, south of the location. It does not appear that this corrective action has been addressed.		
Corrective Action:	Comply with Rule 606 and remove debris. (Original CA Date: 11/27/2023).	Date:	11/27/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type:	#		corrective date
Comment:	Previous FIR (doc #708200709) documented that there was no wildlife netting at day tank next to wellhead. It appears that netting has been installed around the secondary containment.		
Corrective Action:			Date:
Type: Deadman # & Marked	#		
Comment:	Northeast deadman/guyline anchor (t-post) has fallen down and needs to be reinstalled to comply with Rule 1003.a.		
Corrective Action:			Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	219731	Type:	WELL	API Number:	075-06955	Status:	PR	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	312228	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING

Comment

Corrective Action Date

1002b. SOIL REMOVAL AND
SEGREGATION

Comment

Corrective Action Date

1002c. PROTECTION OF SOILS

Comment

Corrective Action Date

1002E. SURFACE DISTRURBANCE MINIMIZATION

Comment

Corrective Action Date

1003a. Waste and Debris removed?

Comment

Corrective Action Date

Unused or unneeded equipment onsite?

Comment

Corrective Action Date

Pit, cellars, rat holes and other bores closed?

Comment

Corrective Action Date

Guy line anchors marked?

Comment

Corrective Action Date

1003b. Area no longer in use? _____ Production areas stabilized ? Fail

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment Interim areas appear to be progressing towards Rule 1003 standards and regulations with evidence of desirable species consistent with the adjacent reference areas observed. However, portions of the interim/production areas are experiencing erosion degradation and will need to be repaired, stabilized, and revegetated to comply with Rule 1003 (see Stormwater Section for additional information). This location will remain "In-Process" until the interim and production areas have been stabilized and reclaimed, at which point the location will be reinspected for compliance with Rule 1003. Refer to attached inspection photos.

Corrective Action _____ Date _____

Overall Interim Reclamation In Process**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:		Date _____
Corrective Action:		
Overall Final Reclamation	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<div>Comment: <div>Previous FIR (doc #708200709) documented that severe erosion degradation was evident along the outer portion of the production areas. No apparent stormwater control measures/BMPs were observed that would prevent continued erosion degradation or sediment/soil from exiting off location into the adjacent drainage. During this inspection, it was observed that no apparent stormwater control measures/BMPs have been implemented or existing erosion degradation has been repaired.</div></div>						
Corrective Action: <div>Comply with Rue 1002.f. (Original CA Date: 11/27/2023).</div>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708201674	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6738502