

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/30/2024

Submitted Date:

10/09/2024

Document Number:

709100436

FIELD INSPECTION FORMLoc ID 336999 Inspector Name: Heibel, Krystal On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Krystal Heibel		krystal.heibel@state.co.us	
Dolezal, Pat		pat.dolezal@ownresources.com	Inspections
Kyle Waggoner		kyle.waggoner@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
419083	PIT	AC			-	WARREN FARMS 4-31	EI

General Comment:

This is an environmental progress inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. Photos attached to document site conditions.

Inspected Facilities									
Facility ID:	419083	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date:

Pits: NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID: 419083	Lat: 40.353070	Long: -102.532600
-------	--------	----------------	----------------	-------------------

Reference Point: Other: Length: Width:

Lining:

Liner Type: OtherLiner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: NoneFencing Condition: Inadequate

Comment: Two feet of freeboard was not observed in the pit; Lower fluid level so at least two feet of freeboard exists per Rule 909.c.

Corrective Action

Date:

Netting:

Netting Type:Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:Oil Accumulation:2+ feet Freeboard:

Comment:

Corrective Action

Date:

Attached Documents

You can go to ECMC Images (https://ecmc.state.co.us/weblink/) and search by document number:

Document Num	Description	URL
709100437	Pics	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6738936