

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/03/2024

Submitted Date:

10/03/2024

Document Number:

696306796

FIELD INSPECTION FORMLoc ID 318871 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 30560

Name of Operator: FORTITUDE EXPLORATION CO

Address: P O BOX 5417

City: NAVARRE State: FL Zip: 32566

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

11 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gregory Dillion		gregory_dillon@yahoo.com	
Wolfe, Stephen		stephen.wolfe@state.co.us	
Jor Culek		j.culek@charter.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242350	WELL	TA	06/01/2023	OW	123-10141	U S A 21-6	TA

General Comment:

This is a Well and Tank Battery Audit

Location**Lease Road:**

Type	Access		
comment:	Access Road to Well is inaccessible due to Fencing Wire over Cattleguard.		
Corrective Action:	Provide Access to Well per Rule 204	Date:	10/18/2024

Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds through out the entire Location; see photos		
Corrective Action:	Comply with Rule 606	Date:	10/18/2024
Type	UNUSED EQUIPMENT		
Comment:	Unused Black Barrel on East side of Pit; see photos		
Corrective Action:	Comply with Rule 606	Date:	10/18/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:

Type: Vertical Heater Treater	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
----------	---	----------	------	---------	--------	--

CRUDE OIL	1	300 BBLS	STEEL AST		40.962370,-103.687080	
Comment:						
Corrective Action:					Date:	
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:					Date:	
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:		Shares berm with the Crude Oil Tanks				
Corrective Action:					Date:	
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 242350

Type: WELL

API Number: 123-10141

Status: TA

Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder:

Comment: TA - Since 06.01.2023

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/11/2021

Annual Brhd Completed? No

Last Brhd Test Results

Initial Surf Csg Pressure: 0

Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: No current Bradenhead Test on File; Last Form 17 03.11.2021

10/18/2024

Corrective Action: Perform Bradenhead Test and submit Form 17 per Rule 419.c

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced Water

Lined:

Pit ID:

Lat: 40.962040Long: -103.687000Reference Point: SEOther: Length: 30Width: 30**Lining:**

Liner Type:

Liner Condition:

Comment: Corrective Action Date: **Fencing:**

Fencing Type:

Fencing Condition:

Comment: Corrective Action Date: **Netting:**

Netting Type:

Netting Condition:

Comment: Corrective Action Date:

Anchor Trench Present:

Oil Accumulation: NO2+ feet Freeboard: YESComment: Corrective Action Date: **ECMC Comments**

Comment	User	Date
Routine Field Audit. No current Bradenhead Form 17 on File. Weeds throughout the Location. Access to Well is blocked at Cattleguard. Unused Black Barrel Drum at Pit	petrie	10/03/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403944642	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6731886
696306797	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6731880