

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/09/2024

Submitted Date:

10/10/2024

Document Number:

717300068

**FIELD INSPECTION FORM**

Loc ID 332175 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 10633  
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC  
Address: 555 17TH STREET SUITE 3700  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270729	WELL	TA	02/01/2024	GW	123-21933	HURT 33-11	PA
336375	LOCATION	AC			-	GRANT/HURT SWSE MULTI WELL 23-11	EG

**General Comment:**

ECMC Engineering Integrity Inspection; Flowline Inspection  
Photos uploaded

**Inspected Facilities**

Facility ID: 270729 Type: WELL API Number: 123-21933 Status: TA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 336375 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
Well is plugged and abandoned (Hurt 33-11); ECMC form 42 notice of start of plugging operations doc #403667005 received on 01/25/2024. The facility/ tank battery has been decommissioned; tanks and equipment removed. No flowlines/ risers observed at facility/ battery area. Remediation work is in progress.	maclarej	10/10/2024
As outlined on ECMC form 19 spill report Doc #403950134 received on 10/08/2024: While conducting facility decommissioning activities at Crestone's Hurt 33-11 wellhead and associated flowline, historical impacts were discovered at the flowline riser adjacent to Hurt 43-11, Grant 23-11, Grant 3-6-44, Grant 2-8-11 and Hurt 7-8-11 wellheads. The impacted soil will be removed and hauled for disposal.	maclarej	10/10/2024
In addition to routine AVO inspections, Crestone implemented an upgraded integrity management program focusing on the reduction of internal corrosion related releases. This program includes increased pressure testing and preventative maintenance frequencies, installation of anodes and fluid detection kill switches on tanks and production vessels, and updating facility designs to utilize more corrosion resistant materials.		

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300070	View of location; OOS GMR	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6741470">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6741470</a>
717300071	View towards PA well; looking north	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6741471">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6741471</a>