

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/03/2024

Submitted Date:

10/04/2024

Document Number:

713601494**FIELD INSPECTION FORM**Loc ID 324837 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 83130Name of Operator: STRACHAN EXPLORATION INCAddress: 992 S 4TH AVE SUITE 100-461City: BRIGHTON State: CO Zip: 80601**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Harms, Jason		Jason@strachanexploration.com	
BEAR STACY		stacy@strachanexploration.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213033	WELL	SI	01/01/2024	OW	061-06394	STAVELY 1-26	RI

**General Comment:**

This is a follow up of the previous reclamation inspection #713601035.  
See attached photos and additional details within this report.

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	New sign was installed at the wellhead.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	There are unused parts near the pumpjack that need to be removed.		
Corrective Action:	Comply with Rule 606.	Date:	10/18/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: The container was removed and stained soils appear to be mostly cleaned up.

☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	The fence around the pump jack is inadequate to prevent livestock entry and is not maintained. There is an opening at the tank battery fence and the 2 wires will not keep livestock out. Previous corrective action has not been completed.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules	Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403946907	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6733954">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6733954</a>
713601495	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6733937">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6733937</a>