



FORM  
INSP  
  
Rev  
X/20

State of Colorado  
Oil and Gas Conservation Commission  
1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
10/03/2024  
Submitted Date:  
10/04/2024  
Document Number:  
708302864

Loc ID  
334882

Inspector Name:  
Morris, Matthew

On-Site Inspection ☐  
2A Doc Num:

Operator Information:  
ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

Status Summary:  
☒ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED  
  
Findings:  
8 Number of Comments  
1 Number of Corrective Actions  
☒ Corrective Action Response Requested  
  
ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:  
Contact Name Phone Email Comment  
, TEP COGCCInspectionReports@terraep.com

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211413	WELL	PR	10/14/1997	GW	045-07173	FEDERAL GM 22-3	PR
273257	WELL	PR	03/21/2005	GW	045-10223	FEDERAL GM 322-3	PR
273258	WELL	PR	03/25/2005	GW	045-10222	FEDERAL GM 422-3	PR
273259	WELL	PR	03/17/2005	GW	045-10221	FEDERAL GM 522-3	PR

General Comment:  
CECMC Inspection Report Summary  
  
On 10/3/2024 at approximately 11:40, Compliance Inspector Matthew Morris conducted a follow-up inspection at TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SEnw at Location ID #334882 in Garfield County, Colorado.  
  
During the inspection, the following compliance issues were observed:  
  
1) Open-ended line of separator  
  
A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.  
  
This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Date Run: 10/11/2024 Doc [#708302864]

Page 1 of 6

**Location**Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970)285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

**Equipment:**

Type: Gas Meter Run	# 4		corrective date
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 4	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 4	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 4	
Comment:	Open-ended line on separator.	
Corrective Action:	Secure equipment to comply with Rule 608.e.	Date: 10/09/2024

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	500 gal	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbls	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				



Inspected Facilities									
Facility ID:	211413	Type:	WELL	API Number:	045-07173	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	273257	Type:	WELL	API Number:	045-10223	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	273258	Type:	WELL	API Number:	045-10222	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	273259	Type:	WELL	API Number:	045-10221	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
		Gravel				
Compaction						
Ditches						
		Sediment Traps				
Sediment Traps						
Rip Rap						
		Culverts				
		Check Dams				
		Compaction				
		Rip Rap				
Berms						
		Ditches				

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403947066	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6734154">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6734154</a>
708302865	Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6734148">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6734148</a>