

Inspection Photos

10/08/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335426

Inspection Doc: 696206363

Garfield County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335426



Photo 1: Photos 1-2 taken from the north end of the Location. Photos provide an overview from east, southeast, southwest to west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335426



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335426



Photo 3: PVC pipe at wells open at end. Pipe requires covering to prevent wildlife access.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335426



Photo 4: Line at tank missing cap/plug.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335426



Photo 5: Photo taken from the tank battery facility's secondary containment BMP- BMP no longer sufficiently impervious to contain a spill or release.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335426



October 8, 2024



October 8, 2024

Photo 6: Culverts on the Location are filling with sediment. Maintenance advised prior to failure.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335426



Photo 7: Photos 7-8 taken from along the northern perimeter of the working pad surface. BMPs to manage runoff from these areas have not been implemented. Photos examples showing areas where concentrated stormwater runoff is discharging from the pad onto the fill slopes, and where degradation is becoming evident; continued discharge from these points without proper BMPs will likely result in gully erosion, sediment transport with sediment deposition impacting vegetation establishing on the interim areas.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335426



Photo 8: See comments under photo 7.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources