

Inspection Photos

10/08/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335654

Inspection Doc: 696206369

Garfield County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335654



Photo 1: Photos taken from the access road/Location entrance. Stormwater diversion ditches have not been maintained in proper functioning condition resulting in runoff onto the road and Location and persisting degradation.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335654



Photo 2: Photos taken from the sediment trap on the southeast end of the pad. Photos show the inlet/outlet have not been installed or maintained with a properly engineered inlet/outlet. Degradation to the control has persisted.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335654



Photo 3: Photo taken from the sediment trap on the southeastern end of the Location. Photo shows BMP remains in disrepair; control has not been constructed with an engineered outlet resulting in gully erosion and degradation.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335654



Photo 4: Photo taken from the sediment trap on the southeastern interim areas of the Location. Photo shows BMP remains in disrepair; control has not been constructed with an engineered inlet resulting in gully erosion and degradation.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335654



Photo 5: Photo taken from the sediment trap on the southeastern interim areas of the Location. Photo shows BMP remains in disrepair; control has not been constructed with an engineered inlet resulting in gully erosion and degradation.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335654



Photo 6: Photo taken from the sediment trap on the southeastern interim areas of the Location. Photo shows BMP remains in disrepair; control has not been constructed with an engineered inlet resulting in gully erosion and degradation.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335654



Photo 7: Continued from photo 6. Hard hat in photo used for reference.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335654



Photo 8: BMPs to stabilize the working pad surface have not been installed or maintained. Degradation/tracking has persisted.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335654



Photo 9: Continued from photo 8.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335654



October 8, 2024



October 8, 2024

Photo 10: Photos examples of erosion degradation and anchors missing required marking.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources