

# Interim Reclamation and Stormwater Inspection

September 10, 2024

Operator: FULCRUM ENERGY OPERATING # 10805

Location ID: 445005

Inspection Document #: 712300060

Jackson County, CO

Logan Maxwell  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: Surprise Unit 0680 S9

Location ID: 445005



**Photo 1.** Photo taken from the entrance of Location, illustrating Operator's sign.



**Photo 2.** Photo taken the entrance of the Location, facing SW. Weeds observed growing on the berms and on other portions of the perimeter.



## Inspection Photos

Location Name: Surprise Unit 0680 S9

Location ID: 445005



**Photo 3.** Photo taken 4/15/2024 from the southeastern working pad surface, facing East. Photo illustrates a snow plow pile with random debris.



**Photo 4.** Photo taken from the southeastern working pad, facing North. Photo illustrates that Operator removed snow plow pile with random debris.

Inspection Photos  
Location Name: Surprise Unit 0680 S9  
Location ID: 445005



**Photo 5.** Photo taken from the southern working pad surface, facing SE. Photo illustrates the stabilized outlet. At the time of this inspection, there was no sediment discharge off of the Location.



## Inspection Photos

Location Name: Surprise Unit 0680 S9

Location ID: 445005



**Photo 6.** Photo taken from the eastern working pad surface, facing East. Photo illustrates revegetation of the fill slopes are in process. Operator shall continue to monitor and manage until Location reaches 1003 standards.



**Photo 7.** Photo taken from the eastern working pad, facing SE. Photo illustrates a portion of the topsoil stockpile with temporary BMPs (erosion control netting). Operator shall continue to monitor and manage until Location reaches 1002 standards.



Inspection Photos  
Location Name: Surprise Unit 0680 S9  
Location ID: 445005



**Photo 8.** Photo taken 4/15/2024 from the southern working pad surface, facing Southeast. Photo illustrates the equipment and secondary containment lacks wildlife protection.



**Photo 9.** Photo taken from the southern working pad, facing SE. Photo illustrates that wildlife BMPs were implemented on secondary containment.