

Inspection Photos

Location Name: FLETCHER GULCH 3-21

Location ID: 316580

Inspection Date: September 24, 2024



Location sign. Improper abandonment of flowline or crude oil transfer line (not purged, depressurized, risers cut 3' below grade, ends sealed, equipment removed) per 1105. Disconnected flowline risers not OOSLAT. Form 44 notice of abandonment not filed within 30 days. Local gov't designee and UNCC not contacted.

Sep 24, 2024 1:08:54 PM
+40.0868N -108.6094W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 3-21

Location ID: 316580

Inspection Date: September 24, 2024

Well head.

Sep 24, 2024 1:10:05 PM
+40.0866N -108.6092W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 3-21

Location ID: 316580

Inspection Date: September 24, 2024

Unnecessary equipment.

Sep 24, 2024 1:09:55 PM
+40.0866N -108.6091W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 3-21

Location ID: 316580

Inspection Date: September 24, 2024

FLETCHER GULCH 3-21
location.

Sep 24, 2024 1:08:58 PM
+40.0868N -108.6094W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources