


Inspection Photos
Location Name: Haley Ray 13-21
Location ID: 305413



Energy and Carbon Management Commission
40.90169, -104.21801, 5103.6ft
10/08/2024 12:25:23

Photo 1 – Pumping Unit



Energy and Carbon Management Commission
40.90171, -104.21799, 5094.4ft
10/08/2024 12:25:27

Photo 2 – Well Sign

Inspection Photos
Location Name: Haley Ray 13-21
Location ID: 305413



Photo 3 – Wellhead



Photo 4 – Heater Treater

Inspection Photos
Location Name: Haley Ray 13-21
Location ID: 305413



Photo 5 – Heater Treater and ECD



Photo 6 – Tank Battery

