

## Inspection Photos

**Operator: AMERICAN HELIUM OPERATING LLC - 10841**

**Location Name: ANDY'S MESA FEDERAL #36      API #: 05-113-06124**

**Location Name: ANDY'S MESA UNIT #59      API #: 05-113-06135**

**Location ID: 334332**

**Inspection Date: 10/10/2024    Inspection Doc#: 693807804**



**Location overview looking NW**



**Wellheads with fence and signs**

## Inspection Photos

**Operator: AMERICAN HELIUM OPERATING LLC - 10841**

**Location Name: ANDY'S MESA FEDERAL #36      API #: 05-113-06124**

**Location Name: ANDY'S MESA UNIT #59      API #: 05-113-06135**

**Location ID: 334332**

**Inspection Date: 10/10/2024    Inspection Doc#: 693807804**



**Separators and Meter housings**



**Tank Battery.**

## Inspection Photos

Operator: AMERICAN HELIUM OPERATING LLC - 10841

Location Name: ANDY'S MESA FEDERAL #36      API #: 05-113-06124

Location Name: ANDY'S MESA UNIT #59      API #: 05-113-06135

Location ID: 334332

Inspection Date: 10/10/2024    Inspection Doc#: 693807804



FLIR video of leaking enardo valve on tank battery.

