

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Savage RWF 23-25 Pad

Location ID: 432398



Photo # 5320 From entrance to location



Photo # 5321 From entrance to location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Savage RWF 23-25 Pad

Location ID: 432398




Photo # 5322 Location



Photo # 5323 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Savage RWF 23-25 Pad

Location ID: 432398



Photo # 5324 Location



Photo # 5325 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Savage RWF 23-25 Pad

Location ID: 432398



Photo # 5326 Location

Photo # 5327 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Savage RWF 23-25 Pad

Location ID: 432398



Photo # 5328 Location



Photo # 5329 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Savage RWF 23-25 Pad

Location ID: 432398



Oct 14, 2024 at 2:06:04 PM  
CO



Oct 14, 2024 at 2:25:27 PM  
CO

Photo # 5330 Location

Photo # 5331 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Savage RWF 23-25 Pad

Location ID: 432398



**Photo # 5332 Mechanical Condition – possible leak on chemical tank pump/equipment**



**Photo # 5333 Mechanical Condition – possible leak on chemical tank pump/equipment**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Savage RWF 23-25 Pad

Location ID: 432398



**Photo # 5334 Mechanical Condition – possible leak on chemical tank pump/equipment**



**Photo # 5335 Mechanical Condition – possible leak on chemical tank pump/equipment**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Savage RWF 23-25 Pad

Location ID: 432398




Photo # 5336 Wellhead sign weathered & cracking




Photo # 5337 Wellhead sign weathered & cracking