

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/09/2024

Submitted Date:

10/09/2024

Document Number:

716200894

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: _____ On-Site Inspection
 306674 _____ Carlile, Craig _____ 2A Doc Num: _____
Operator Information:
 ECMC Operator Number: _____ 47120 _____
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP _____
 Address: P O BOX 173779 _____
 City: _____ DENVER _____ State: _____ CO _____ Zip: _____ 80217- _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 6 _____ Number of Comments
- 2 _____ Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Oxy		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290478	WELL	SI	05/01/2023	OW	123-25101	CANEPA 6-13	PA

General Comment:

This is a corrective action Plug & Abandonment audit.
 Well has been plugged and is awaiting casing cut and cap.
 No legible sigage at wellhead.
 Weeds at wellhead.
 Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 11/11/2024

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds at wellhead		
Corrective Action:	Comply with Rule 606		Date: 10/17/2024

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Pipe panels		
Corrective Action:			Date:

Equipment:			corrective date
Type: Plunger Lift	# 0		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 290478 Type: WELL API Number: 123-25101 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>This is a corrective action Plug & Abandonment audit. Well has been plugged and is awaiting casing cut and cap. No legible sigage at wellhead. Weeds at wellhead. Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect.</p>	carlilec	10/09/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403950907	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6739180
716200895	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6739178