

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/15/2024

Submitted Date:

10/16/2024

Document Number:

710100286**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Anderson, Laurel 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Peterson, John	303-550-8872	jpetereson@kpk.com	Director EHS & Compliance
Brown, Kari		kari.oakman@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
Kauffman, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
475986	OFF-LOCATION FLOWLINE	AC	02/05/2021		-	Wellhead Line	EI
487675	SPILL OR RELEASE	AC			-	Lanson Farms 15 Flowline	EI

General Comment:

This is an Environmental inspection conducted October 15, 2024, by ECMC Environmental Protection Specialist, Laurel Anderson to document remediation progress at the Lanson Farms 15 Flowline Spill (Spill ID #485936).

Corrective actions from previous inspections that have not been addressed are still applicable. Any comments/conditions of approval from previously denied/approved forms that have not been addressed are still applicable.

Photos attached to document site conditions at the time of inspection. No discernible change was observed since previous inspection Doc #710100254.

Reported Flowline Spill Date of Discovery: 08/19/2024

Operator personnel were on location at the time of inspection. While on location Operator personnel repaired a section of fencing that had fallen into the open excavation.

A hydrocarbon sheen was previously observed on groundwater within the open excavation
Stained soil remains insitu and is visible within the open excavation
Liner beneath E&P Waste Stockpiled on location has been punctured and is not adequate

Spill excavation is located:

- Within the Town of Frederick
- 70' from the mapped flowline
- <45' from mapped wetlands
- <55' from surface water (Godding Hollow Stream)

Inspected Facilities									
Facility ID:	475986	Type:	OFF-	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	487675	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710100287	2024_1015_Lanson Farms 15 Flowline Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6749110