

Inspection Photos

Location Name: COCKROFT USX A-66N64W/11SENE

Location #: 333034



Colorado Energy & Carbon Management Commission
Weld County
+40.501901, -104.509728
314° NW
2024-10-14 15:23

Photo #1

Cockroft USX A 11-8 (123-24711) Wellsite

Workover | WK

Plugging Ops; Workover: kill well, pull tubing



Colorado Energy & Carbon Management Commission
Weld County
+40.502023, -104.509145
297° NW
2024-10-14 15:24

Photo #2

Cockroft USX A 11-8 Wellsite

Workover | WK

Plugging Ops; Workover: kill well, pull tubing

Site safety signage



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: COCKROFT USX A-66N64W/11SENE
Location #: 333034



Photo #3

Cockroft USX A 11-8 Wellsite

Workover | WK

Plugging Ops; Workover: kill well, pull tubing

Wellsite entrance




Photo #4

Cockroft USX A 11-8 Wellsite

Workover | WK

Plugging Ops; Workover: kill well, pull tubing

JSA: 2024-10-14

