

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/24/2024

Submitted Date:

10/10/2024

Document Number:

699700416

FIELD INSPECTION FORMLoc ID 316583 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10384

Name of Operator: GENESIS GAS & OIL COLORADO LLC

Address: 1141 NORTH LOOP 1604 E 105-414

City: SAN ANTONIO State: TX Zip: 78232

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Roberts, James		j75rober@blm.gov	BLM meeker
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286502	WELL	PR	11/01/2022	CBM	103-10897	FLETCHER GULCH 4-24	EI

General Comment:

ECMC Environmental Inspection. All previous unresolved CAs for this location still apply to this inspection.

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
Good Housekeeping:				
Type	OTHER			
Comment:	Unnecessary equipment throughout the location.			
Corrective Action:	Comply with Rule 606.			Date:
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
	Pump Jack			
Comment:	Potentially impacted material adjacent to the pump jack.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date:
Produced Water	WELLHEAD			
Comment:	Potentially impacted material adjacent to the wellhead.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date:
In Containment: No				
Comment:				
<input checked="" type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 286502 Type: WELL API Number: 103-10897 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403952524	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6740631
699700417	20240924	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6740630