

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/17/2024

Submitted Date:

10/17/2024

Document Number:

716201044**FIELD INSPECTION FORM**Loc ID 437535 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------|---------------------------------|
| , Oxy | | ECMCInspections@Oxy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 437534 | WELL | PR | 12/01/2022 | OW | 123-39584 | DOUTHIT 16C-27HZ | PR |
| 437536 | WELL | PR | 09/01/2021 | GW | 123-39585 | DOUTHIT 9C-27HZ | PR |
| 437537 | WELL | PR | 01/01/2021 | GW | 123-39586 | DOUTHIT STATE 38N-27HZ | PR |
| 437538 | WELL | PR | 08/01/2021 | GW | 123-39587 | DOUTHIT 39N-27HZ | PR |
| 437539 | WELL | PR | 02/01/2021 | OW | 123-39588 | DOUTHIT 40N-27HZ | PR |

General Comment:[This is a corrective action Wellhead audit.](#)[Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect.](#)

LocationOverall Good: ☒

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | |
|---------------------------|-------------|
| Emergency Contact Number: | |
| Comment: | |
| Corrective Action: | Date: _____ |

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--------------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Metal Picket | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---------------------------------|----------|---------------------|---------|--------|
| | | | CENTRALIZED BATTERY | | , |
| Comment: | Battery location number: 437533 | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
| | | | | |

| Inspected Facilities | | | |
|--|------------|--|----------------------------------|
| Facility ID: 437534 | Type: WELL | API Number: 123-39584 | Status: PR Insp. Status: PR |
| Producing Well | | | |
| Comment: PR | | | |
| Corrective Action: | | Date: | |
| BradenHead | | | |
| Date of Last Brhd Test: 07/31/2024 | | Annual Brhd Completed? _____ | |
| Last Brhd Test Results | | Initial Surf Csg Pressure: 7 Fluid Type: None | |
| End Surf Csg Pressure: -- | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | |
| Facility ID: 437536 | Type: WELL | API Number: 123-39585 | Status: PR Insp. Status: PR |
| Producing Well | | | |
| Comment: PR | | | |
| Corrective Action: | | Date: | |
| BradenHead | | | |
| Date of Last Brhd Test: 07/30/2024 | | Annual Brhd Completed? _____ | |
| Last Brhd Test Results | | Initial Surf Csg Pressure: 2 Fluid Type: None | |
| End Surf Csg Pressure: -- | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | |
| Facility ID: 437537 | Type: WELL | API Number: 123-39586 | Status: PR Insp. Status: PR |
| Producing Well | | | |
| Comment: PR | | | |
| Corrective Action: | | Date: | |
| BradenHead | | | |
| Date of Last Brhd Test: 07/31/2024 | | Annual Brhd Completed? _____ | |
| Last Brhd Test Results | | Initial Surf Csg Pressure: 4 Fluid Type: None | |
| End Surf Csg Pressure: -- | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | |
| Facility ID: 437538 | Type: WELL | API Number: 123-39587 | Status: PR Insp. Status: PR |
| Producing Well | | | |
| Comment: PR | | | |
| Corrective Action: | | Date: | |

| | | | |
|------------------------------------|-------------------------------|------------------------------|--|
| BradenHead | | | |
| Date of Last Brhd Test: 07/31/2024 | | Annual Brhd Completed? _____ | |
| Last Brhd Test Results | Initial Surf Csg Pressure: 20 | Fluid Type: None | |
| | End Surf Csg Pressure: -- | | |
| Comment: | <div></div> | | |
| Corrective Action: | <div></div> | Date: _____ | |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 437539 | Type: WELL | API Number: 123-39588 | Status: PR | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

| | | | |
|-----------------------|-------------|-------|-------------|
| Producing Well | | | |
| Comment: | PR | | |
| Corrective Action: | <div></div> | Date: | <div></div> |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

| ECMC Comments | | |
|--|----------|------------|
| Comment | User | Date |
| This is a corrective action Wellhead audit. Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect. | carlilec | 10/17/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 716201045 | Photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6750073 |