

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/17/2024

Submitted Date:

10/17/2024

Document Number:

713301191**FIELD INSPECTION FORM**Loc ID 434399 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**19 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434393	WELL	SI	03/01/2024	OW	001-09772	Willow Bend LD 18-22HN	SI
434394	WELL	SI	04/01/2024	OW	001-09773	Willow Bend LD 18-23HN	SI
434395	WELL	PR	02/01/2023	OW	001-09774	Willow Bend 18-22HC	PR
434396	WELL	SI	04/01/2024	OW	001-09775	Willow Bend LD 18-37HN	SI
434403	WELL	SI	03/01/2024	OW	001-09777	Willow Bend LD 18-366HC	SI
440563	WELL	SI	03/01/2024	OW	001-09841	Willow Bend LD 18-361HC	SI

**General Comment:**

well site and facility inspection

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	good		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	good		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	good, six wells		
Corrective Action:		Date:	
Type	OTHER		
Comment:	entrance, good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	LOCATION		
Comment:	post and wire with entrance gate		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment:	insturment supply tank		
Corrective Action:		Date:	
Type: Bird Protectors	# 13		
Comment:			
Corrective Action:		Date:	
Type: FWKO	# 1		

Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 12		
Comment: electric/automation panels			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 4		
Comment: 1-sales, 2-injection, 1-recovery			
Corrective Action:			Date:
Type: Bradenhead	# 6		
Comment: piped to surface, six wells			
Corrective Action:			Date:
Type: Plunger Lift	# 6		
Comment: six wells			
Corrective Action:			Date:
Type: Emission Control Device	# 7		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	150 Bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment: shared with crude tanks					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	16	300 BBLS	STEEL AST		,

Comment:		
Corrective Action:		Date:

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

API Number
123-09772
123-09774
123-09775
123-09841
123-09773
123-09777

API Number	AirsID
------------	--------

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 434393 Type: WELL API Number: 001-09772 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: Valves appeared to be closed at time of inspectionCorrective Action:  Date: **BradenHead**Date of Last Brhd Test: 04/17/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action:  Date: 

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 434394 Type: WELL API Number: 001-09773 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: Valves appeared to be closed at time of inspectionCorrective Action:  Date: **BradenHead**Date of Last Brhd Test: 04/17/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action:  Date: 

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 434395 Type: WELL API Number: 001-09774 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: Valves appeared to be closed at time of inspectionCorrective Action:  Date: **BradenHead**Date of Last Brhd Test: 04/17/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action:  Date: 

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 434396 Type: WELL API Number: 001-09775 Status: SI Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In☐ Temporarily Abandoned

Reminder: EQUIPMENT ONSITE

Comment: Valves appeared to be closed at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/17/2024

Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 434403

Type: WELL

API Number: 001-09777

Status: SI

Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In☐ Temporarily Abandoned

Reminder: EQUIPMENT ONSITE

Comment: Valves appeared to be closed at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/17/2024

Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 440563

Type: WELL

API Number: 001-09841

Status: SI

Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In☐ Temporarily Abandoned

Reminder: EQUIPMENT ONSITE

Comment: Valves appeared to be closed at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/17/2024

Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
Audit of scout card and related documents Routine inspection  This inspection does not nullify any orders or NOAV from the ECMC This is a continuing education inspection	kesterm	10/17/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713301192	site pic	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6750579">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6750579</a>