

## Inspection Photos

Location: CHEVRON USA INC SKR-66S98W/4NESW

Location ID: 336049

Date: 10/16/2024



Oct 16, 2024 at 2:13:37 PM  
+39.559955,-108.339193 ±4.72m

Photo # 7475 Entrance to location



Oct 16, 2024 at 2:36:27 PM  
+39.559607,-108.339229 ±4.73m

Photo # 7494 Location



## Inspection Photos

Location: CHEVRON USA INC SKR-66S98W/4NESW

Location ID: 336049

Date: 10/16/2024



Photo # 7476 Location



Photo # 7483 Location



## Inspection Photos

Location: CHEVRON USA INC SKR-66S98W/4NESW

Location ID: 336049

Date: 10/16/2024



Photo # 7484 Location



Photo # 7492 Location



## Inspection Photos

Location: CHEVRON USA INC SKR-66S98W/4NESW

Location ID: 336049

Date: 10/16/2024



Photo # 7501 NW corner of location



Photo # 7502 NE corner of location



## Inspection Photos

Location: CHEVRON USA INC SKR-66S98W/4NESW

Location ID: 336049

Date: 10/16/2024



Oct 16, 2024 at 2:49:13 PM  
+39.559302,-108.337981 ±4.70m



Oct 16, 2024 at 2:51:12 PM  
+39.558825,-108.338692 ±4.71m

Photo # 7503 SE corner of location

Photo # 7504 SW corner of location