

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 146-19 Pad

Location ID: 335345



Photo # 5999 From entrance to location



Photo # 6000 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 146-19 Pad

Location ID: 335345



Photo # 6001 Location



Photo # 6002 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 146-19 Pad

Location ID: 335345



Photo # 6003 Location



Photo # 6004 RMV 146-19 wellhead sign cracking & peeling/some required info starting to become illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 146-19 Pad

Location ID: 335345



Photo # 6005 RWF 344-19 wellhead sign cracking & peeling



Photo # 6006 RWF 444-19 wellhead sign cracking & peeling

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 146-19 Pad

Location ID: 335345



Photo # 6007 Battery sign cracking & peeling/some info starting to become illegible

