

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/09/2024

Submitted Date:

10/21/2024

Document Number:

701104089**FIELD INSPECTION FORM**Loc ID 312669 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1700 LINCOLN ST STE 3950City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
COGCC, Laramie	970-248-0497	cogccnotifications@laramie-energy.com	<a href="#">All inspections</a>
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259339	WELL	SI	05/01/2024	GW	077-08726	WAGON TRACK FEDERAL 11-1	EG
487350	SPILL OR RELEASE	AC	08/23/2024		-	WT 11-1 Tank Release	EG

**General Comment:**[Flowline Integrity Inspection and Tank Integrity Inspection](#)[Original production tank has been remove due integrity failure which lead to a spill/release WT 11-1 Tank Release id. #487350 reported 07/22/2024.](#)[Replacement tank is in a dirt berm with ploy liner.](#)[Continue to monitor this temporary berm until tank is permanently installed.](#)[2" riser inside of the original production tank containment area needs OUT OF SERVICE LOCKS AND TAGS \(OOSLAT\).](#)

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Flow Line

# 1

Comment: 2" riser inside of the original production tank containment area needs OUT OF SERVICE LOCKS AND TAGS (OOSLAT).

Corrective Action: Ensure flowline(s) are isolated and depressurized; associated wells and isolation valves are SI/ OOSLAT to prevent unintentional release per 1102.j.7 (prior to and time of repair)

Date: 10/25/2024

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	Original production tank has been remove due integrity failure which lead to a spill/release WT 11-1 Tank Release id. # 487350 reported 07/22/2024. Replacement tank is in a dirt berm with ploy liner.  Continue to monitor this temporary berm until tank is permanently installed.			
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 259339	Type: WELL	API Number: 077-08726	Status: SI	Insp. Status: EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 487350	Type: SPILL OR	API Number: -	Status: AC	Insp. Status: EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701104090	Flowline integrity inspection 701104089 photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6755825">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6755825</a>