

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/22/2024

Submitted Date:

10/22/2024

Document Number:

715800188

**FIELD INSPECTION FORM**

Loc ID 318363 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	<a href="#">All Inspections</a>
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241172	WELL	PR	05/01/2024	OW	123-08960	HAUDRICH 2	PR

**General Comment:**

[This is a wellsite audit inspection.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Location is not accessible during normal business hours. Provide key, combinations, or alternate method of access to comply with rule 204.		
Corrective Action:		Date:	

Overall Good:

<b>Emergency Contact Number:</b>	
Comment:	<input style="width: 100%;" type="text"/>
Corrective Action:	<input style="width: 100%;" type="text"/>
	Date: _____

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No \_\_\_\_\_

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 241172 Type: WELL API Number: 123-08960 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary                      On Tuesday 10-22-2024 at approximately 1320 hrs.                      I, Inspector Robbie Revas, Conducted an audit of the well scout card &amp; related forms followed by an onsite inspection:                      Operator: KP Kauffman                      Location #318336                      API # 05-123-08960                      Well name: Haudrich 2                      County: Weld                      Weather: Sunny &amp; clear                      Temp: 78                      Location: Dry                      While there, I observed wellsite, SI at the time of inspection.                      During this inspection the following possible compliance issues were observed:                      204 Access: Provide key or alternate method of access to comply with rule 204.                      See attached photos.                      I spoke with Mani Silva about the lock not opening with my key &amp; he is going to find out the issue.                      A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	revasr	10/22/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715800189	Location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6756533">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6756533</a>