

Inspection Photos

Location: SG INTERESTS I LTD FEDERAL-610S91W/26SESE

Location ID: 322005

Date: 10/21/2024



Photo # 7653 Entrance to location




Photo # 7672 Location

Inspection Photos

Location: SG INTERESTS I LTD FEDERAL-610S91W/26SESE

Location ID: 322005

Date: 10/21/2024



Oct 21, 2024 at 12:26:31 PM
+39.156686,-107.513558 ±4.72m

Photo # 7655 Location



Oct 21, 2024 at 12:34:19 PM
+39.156920,-107.513647 ±4.70m

Photo # 7660 Location

Inspection Photos

Location: SG INTERESTS I LTD FEDERAL-610S91W/26SESE

Location ID: 322005

Date: 10/21/2024



Photo # 7671 Location



Photo # 7684 Location

Inspection Photos

Location: SG INTERESTS I LTD FEDERAL-610S91W/26SESE

Location ID: 322005

Date: 10/21/2024



Photo # 7685 NE corner of location



Photo # 7686 NW corner of location

Inspection Photos

Location: SG INTERESTS I LTD FEDERAL-610S91W/26SESE

Location ID: 322005

Date: 10/21/2024



Photo # 7687 SW corner of location



Photo # 7688 SE corner of location

Inspection Photos

Location: SG INTERESTS I LTD FEDERAL-610S91W/26SESE

Location ID: 322005

Date: 10/21/2024



Photo # 7662 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 7664 PRV vent line does not comply with CECMC pressure safety device rules