

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/21/2024

Submitted Date:

10/22/2024

Document Number:

713400415

FIELD INSPECTION FORMLoc ID 322005 Inspector Name: Popejoy, Dusty On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 77330

Name of Operator: SG INTERESTS I LTD

Address: 100 WAUGH DR SUITE 400

City: HOUSTON State: TX Zip: 77007

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

15 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Interests, SG		inspection@sginterests.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Toews, Wesley		wtoews@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282932	WELL	PR	05/01/2024	GW	029-06094	FEDERAL 1-26R	PR

General Comment:[CECMC Inspection Report Summary](#)

On 10/21/2024 at approximately 12:24 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection at SG INTERESTS I LTD FEDERAL-610S91W/26SESE at Location ID #322005 in Delta County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

1. PRV vent line does not comply with CECMC pressure safety device rules with a CA date of 10/29/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Location**Lease Road:**

Type	Access		
comment:	Access		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Chemical labeling on tank on separator		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	(866)261-9766/911		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Barbed wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbed wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	PRV vent line does not comply with CECMC pressure safety device rules, please refer to photos		
Corrective Action:	Comply with CECMC pressure safety device rules		Date: 10/29/2024
Type: Other	# 2		
Comment:	Catalytic heaters		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Bradenhead valve is accessible		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		,
Comment:	No telemetry on tank				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	400 BBLs	HEATED STEEL AST		,	
Comment: No telemetry on tank						
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities									
Facility ID:	282932	Type:	WELL	API Number:	029-06094	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
		Ditches				
		Gravel				Sparse to none in sections
Berms						
Gravel						Sparse to none in some areas
Compaction						
Ditches						
		Culverts				

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400416	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6756662