



FORM
INSP

Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
10/15/2024
Submitted Date:
10/15/2024
Document Number:
699506487

FIELD INSPECTION FORM

Loc ID
453676

Inspector Name:
MEDINA, JUSTIN

On-Site Inspection ☐
2A Doc Num: _____

Operator Information:

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments
0 Number of Corrective Actions
☐ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453670	WELL	PR	05/22/2019	OW	123-46247	VERDE 13-7HZ	PR
453671	WELL	PR	05/21/2019	OW	123-46248	VERDE 13-11HZ	PR
453672	WELL	PR	05/14/2019	OW	123-46249	VERDE 13-17HZ	PR
453673	WELL	PR	05/20/2019	OW	123-46250	VERDE 13-13HZ	PR
453674	WELL	PR	05/20/2019	OW	123-46251	VERDE 13-14HZ	PR
453675	WELL	PR	05/21/2019	OW	123-46252	VERDE 13-9HZ	PR
453677	WELL	PR	05/20/2019	OW	123-46253	VERDE 13-15HZ	PR
453678	WELL	PR	05/21/2019	OW	123-46254	VERDE 13-10HZ	PR
453679	WELL	PR	05/21/2019	OW	123-46255	VERDE 13-12HZX	PR
453680	WELL	PR	05/22/2019	OW	123-46256	VERDE 13-8HZ	PR
453681	WELL	PR	05/20/2019	OW	123-46257	VERDE 13-16HZ	PR
453682	WELL	PR	05/12/2019	OW	123-46258	VERDE 13-18HZ	PR

General Comment:

There have been no changes to equipment on location since previous inspection.

Date Run: 10/23/2024 Doc [#699506487]

Page 1 of 4

Location					
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:					Date: _____
Corrective Action:					
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:			Date:		
Flaring:					
Type					
Comment:					
Corrective Action:			Date:		

Inspected Facilities				
Facility ID:	453670	Type:	WELL	API Number: 123-46247 Status: PR Insp. Status: PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	453671	Type:	WELL	API Number: 123-46248 Status: PR Insp. Status: PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	453672	Type:	WELL	API Number: 123-46249 Status: PR Insp. Status: PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	453673	Type:	WELL	API Number: 123-46250 Status: PR Insp. Status: PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	453674	Type:	WELL	API Number: 123-46251 Status: PR Insp. Status: PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	453675	Type:	WELL	API Number: 123-46252 Status: PR Insp. Status: PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	453677	Type:	WELL	API Number: 123-46253 Status: PR Insp. Status: PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	453678	Type:	WELL	API Number: 123-46254 Status: PR Insp. Status: PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	453679	Type:	WELL	API Number: 123-46255 Status: PR Insp. Status: PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	453680	Type:	WELL	API Number: 123-46256 Status: PR Insp. Status: PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	453681	Type:	WELL	API Number: 123-46257 Status: PR Insp. Status: PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	453682	Type:	WELL	API Number: 123-46258 Status: PR Insp. Status: PR
Producing Well				
Comment:	PR			
Corrective Action:				Date:
BradenHead				
Date of Last Brhd Test:	05/14/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results	Initial Surf Csg Pressure:	0	Fluid Type: None	
	End Surf Csg Pressure:	--		
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

ECMC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with ECMC rules. At time of inspection weather conditions were warm, calm, clear.	medinaj	10/15/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699506488	inspection pictures	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6757902