



FORM
INSP

Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
10/15/2024

Submitted Date:
10/15/2024

Document Number:
699506489

FIELD INSPECTION FORM

Loc ID
453447

Inspector Name:
MEDINA, JUSTIN

On-Site Inspection ☐

2A Doc Num: _____

Operator Information:

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

☐ THIS IS A FOLLOW UP INSPECTION

☐ FOLLOW UP INSPECTION REQUIRED

☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453428	WELL	PR	05/07/2019	OW	123-46099	AZUL 13-23HZ	PR
453429	WELL	PR	11/01/2023	OW	123-46100	AZUL 13-25HZ	PR
453430	WELL	PR	05/05/2019	OW	123-46101	AZUL 13-19HZ	PR
453431	WELL	PR	03/01/2023	OW	123-46102	AZUL 13-32HZ	PR
453432	WELL	PR	05/06/2019	OW	123-46103	AZUL 13-13HZ	PR
453433	WELL	PR	05/07/2019	OW	123-46104	AZUL 13-20HZ	PR
453434	WELL	PR	03/01/2023	OW	123-46105	AZUL 13-26HZ	PR
453435	WELL	PR	03/01/2023	OW	123-46106	AZUL 13-24HZ	PR
453436	WELL	PR	05/07/2019	OW	123-46107	AZUL 13-14HZ	PR
453437	WELL	PR	03/01/2023	OW	123-46108	AZUL 13-33HZ	PR
453438	WELL	PR	03/01/2023	OW	123-46109	AZUL 13-28HZ	PR
453439	WELL	PR	03/01/2023	OW	123-46110	AZUL 13-15HZ	PR
453440	WELL	PR	05/11/2019	OW	123-46111	AZUL 13-17HZ	PR
453441	WELL	PR	03/01/2023	OW	123-46112	AZUL 13-31HZ	PR
453442	WELL	PR	03/01/2023	OW	123-46113	AZUL 13-34HZ	PR
453443	WELL	PR	03/01/2023	OW	123-46114	AZUL 13-30HZ	PR
453444	WELL	PR	05/06/2019	OW	123-46115	AZUL 13-21HZ	PR
453445	WELL	PR	03/01/2023	OW	123-46116	AZUL 13-29HZ	PR
453446	WELL	PR	05/09/2019	OW	123-46117	AZUL 13-16HZ	PR
453448	WELL	PR	06/01/2023	OW	123-46118	AZUL 13-27HZ	PR
453449	WELL	PR	05/04/2019	OW	123-46119	AZUL 13-22HZ	PR
453450	WELL	PR	05/06/2019	OW	123-46120	AZUL 13-18HZ	PR

Date Run: 10/23/2024 Doc [#699506489]

Page 1 of 5

General Comment:

There have been no changes to equipment on location since previous inspection.

Location					
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:		<input type="text"/>			
Corrective Action:		<input type="text"/>		Date: <input type="text"/>	
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:		<input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?					
Venting:					
Yes/No	NO				
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>			Date:	<input type="text"/>
Flaring:					
Type	<input type="text"/>				
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>			Date:	<input type="text"/>

Inspected Facilities					
Facility ID: 453428	Type: WELL	API Number: 123-46099	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 453429	Type: WELL	API Number: 123-46100	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 453430	Type: WELL	API Number: 123-46101	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 453431	Type: WELL	API Number: 123-46102	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 453432	Type: WELL	API Number: 123-46103	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 453433	Type: WELL	API Number: 123-46104	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 453434	Type: WELL	API Number: 123-46105	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 453435	Type: WELL	API Number: 123-46106	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 453436	Type: WELL	API Number: 123-46107	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 453437	Type: WELL	API Number: 123-46108	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 453438	Type: WELL	API Number: 123-46109	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 453439	Type: WELL	API Number: 123-46110	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 453440	Type: WELL	API Number: 123-46111	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 453441	Type: WELL	API Number: 123-46112	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 453442	Type: WELL	API Number: 123-46113	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 453443	Type: WELL	API Number: 123-46114	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					

Inspector Name: MEDINA, JUSTIN

Facility ID:	453444	Type:	WELL	API Number:	123-46115	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	453445	Type:	WELL	API Number:	123-46116	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	453446	Type:	WELL	API Number:	123-46117	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	453448	Type:	WELL	API Number:	123-46118	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	453449	Type:	WELL	API Number:	123-46119	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	453450	Type:	WELL	API Number:	123-46120	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/09/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with ECMC rules. At time of inspection weather conditions were warm, calm, clear.	medinaj	10/15/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699506490	inspection pictures	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6757903