


**Operator: XOG**

**Location Name: ALMA 1S-66-2524 PAD**

**Loc ID: 449925**

**Inspection: 708201708**



**CA:** At the time of this inspection, it was observed that the vehicle track out pad did not appear to be properly functioning with evidence of sediment and debris accumulating on the adjacent roadway. ECMC Staff contacted Operator representative (E. Craig) while on location to inform of the vehicle track out. Operator representative stated that the track out would be cleaned with a sweeper and that additional BMPs would be implemented. Maintain vehicle tracking BMPs on the oil and gas location to comply with rule 1002.f.(2)F. Additionally, if material is tracked onto county or public roads, contact the appropriate authority.

**CA Resolution:** Operator has reported that there are actions to pour a concrete apron and add VTC tracking pad to assist with tracking issues. It has been noted that an additional tracking pad has been installed to help and street sweeping will continue as needed.