

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON/TR 24-21-597

Location ID: 324381

Date: 10/23/2024



Photo # 7819 Entrance to location




Photo # 7877 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON/TR 24-21-597

Location ID: 324381

Date: 10/23/2024



Photo # 7822 Location



Photo # 7824 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON/TR 24-21-597

Location ID: 324381

Date: 10/23/2024



Photo # 7828 Location



Photo # 7855 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON/TR 24-21-597

Location ID: 324381

Date: 10/23/2024



Photo # 7876 Location



Photo # 7904 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON/TR 24-21-597

Location ID: 324381

Date: 10/23/2024



Photo # 7905 SW corner of location



Photo # 7906 SE corner of location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON/TR 24-21-597

Location ID: 324381

Date: 10/23/2024



Photo # 7840 Failure to maintain multiple chemical BMP's/chemical tank containments full of fluid/BMP's insufficient to contain possible spill



Photo # 7841 Failure to maintain multiple chemical BMP's/chemical tank containments full of fluid/BMP's insufficient to contain possible spill

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON/TR 24-21-597

Location ID: 324381

Date: 10/23/2024



Photo # 7844 Failure to maintain multiple chemical BMP's/chemical tank containments full of fluid/BMP's insufficient to contain possible spill



Photo # 7847 Failure to maintain multiple chemical BMP's/chemical tank containments full of fluid/BMP's insufficient to contain possible spill

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON/TR 24-21-597

Location ID: 324381

Date: 10/23/2024



Photo # 7849 Failure to maintain multiple chemical BMP's/chemical tank containments full of fluid/BMP's insufficient to contain possible spill



Photo # 7852 Failure to maintain multiple chemical BMP's/chemical tank containments full of fluid/BMP's insufficient to contain possible spill

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON/TR 24-21-597

Location ID: 324381

Date: 10/23/2024



Photo # 7895 Open ended load line



Photo # 7897 Open ended load line

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON/TR 24-21-597

Location ID: 324381

Date: 10/23/2024



Photo # 7899 Open ended load line



Photo # 7907 Wildlife hazard

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON/TR 24-21-597

Location ID: 324381

Date: 10/23/2024



Photo # 7910 Wildlife hazard



Photo # 7912 Wildlife hazard