

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/24/2024

Submitted Date:

10/24/2024

Document Number:

716201096**FIELD INSPECTION FORM**Loc ID 328345 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                   | Comment                         |
|--------------|-------|-------------------------|---------------------------------|
| , Oxy        |       | ECMCInspections@Oxy.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 248076      | WELL | SI     | 03/01/2022  | GW         | 123-15874 | HSR-KENNEDY 14-2 | TA          |

**General Comment:**[This is a routine Wellhead audit.](#)[Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect.](#)

**Location**Overall Good: ☒**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

**Equipment:**

|                    |     |       |                 |
|--------------------|-----|-------|-----------------|
| Type: Plunger Lift | # 0 |       | corrective date |
| Comment:           |     |       |                 |
| Corrective Action: |     | Date: |                 |

**Tanks and Berms:**

| Contents           | #                               | Capacity | Type                | Tank ID | SE GPS |
|--------------------|---------------------------------|----------|---------------------|---------|--------|
|                    |                                 |          | CENTRALIZED BATTERY |         | ,      |
| Comment:           | Battery location number: 331780 |          |                     |         |        |
| Corrective Action: |                                 |          |                     |         | Date:  |

**Paint**

|                  |                      |
|------------------|----------------------|
| Condition        | <input type="text"/> |
| Other (Content)  | <input type="text"/> |
| Other (Capacity) | <input type="text"/> |
| Other (Type)     | <input type="text"/> |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

Inspected Facilities

Facility ID: 248076

Type: WELL

API Number: 123-15874

Status: SI

Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder:

Comment: Well not connected with flow line.  
Tagged Pre-Abandoned  
Tagged OOSLAT

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

| Comment  | User     | Date       |
|--|----------|------------|
| This is a routine Wellhead audit.<br>Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect. | carlilec | 10/24/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 716201097    | Photos      | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6759173">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6759173</a> |