

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/24/2024

Submitted Date:

10/24/2024

Document Number:

713301212**FIELD INSPECTION FORM**Loc ID 434526 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 555 17TH STREET SUITE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**17 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, CivitasResources		Inspections@civiresources.com	<a href="#">all inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434525	WELL	PR	01/07/2019	OW	123-38225	Pratt 4G-29H-P168	PR
434527	WELL	PR	01/07/2019	OW	123-38226	Pratt 4D-29H-P168	PR
434528	WELL	PR	11/16/2017	OW	123-38227	Pratt 4F-29H-P168	PR
434529	WELL	PR	12/01/2021	OW	123-38228	Pratt 4E-29H-P168	PR
434530	WELL	PR	01/07/2019	OW	123-38229	Pratt 4B-29H-P168	PR
434733	WELL	PR	11/16/2017	OW	123-38301	Pratt 4C-29H-P168	PR

**General Comment:**[well site and facility inspection](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	good		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	good, six wells		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	custom metal panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	custom metal panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	post and wirw with entrance gate		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	
Type: LACT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 6		

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 434525 Type: WELL API Number: 123-38225 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 05/13/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 31 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 434527 Type: WELL API Number: 123-38226 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 05/13/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 434528 Type: WELL API Number: 123-38227 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 05/13/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 3 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 434529 Type: WELL API Number: 123-38228 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

<b>BradenHead</b>			
Date of Last Brhd Test:	08/05/2024	Annual Brhd Completed?	Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 49	Fluid Type:	WATER AND GAS
	End Surf Csg Pressure: 0		
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	434530	Type:	WELL	API Number:	123-38229	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

<b>Producing Well</b>			
Comment:	PR, Valves appeared to be open at time of inspection		
Corrective Action:		Date:	

<b>BradenHead</b>			
Date of Last Brhd Test:	05/13/2024	Annual Brhd Completed?	Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 36	Fluid Type:	
	End Surf Csg Pressure: 0		
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	434733	Type:	WELL	API Number:	123-38301	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

<b>Producing Well</b>			
Comment:	PR, Valves appeared to be open at time of inspection		
Corrective Action:		Date:	

<b>BradenHead</b>			
Date of Last Brhd Test:	05/13/2024	Annual Brhd Completed?	Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 0	Fluid Type:	
	End Surf Csg Pressure: 0		
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments		
Comment	User	Date
Audit of scout card and related documents Routine inspection	kesterm	10/24/2024
This inspection does not nullify any orders or NOAV from the ECMC This is a continuing education inspection		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403969506	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6759551">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6759551</a>
713301213	site pic	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6759541">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6759541</a>