

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/14NWNW

Location ID: 335686

Date: 10/24/2024



Photo # 8034 Entrance to location




Photo # 8052 Location

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/14NWNW

Location ID: 335686

Date: 10/24/2024



Oct 24, 2024 at 2:36:57 PM  
+39.618646,-108.251172 ±4.73m  
De Beque

Photo # 8035 Location



Oct 24, 2024 at 2:39:01 PM  
+39.618522,-108.251206 ±4.73m  
De Beque

Photo # 8039 Location

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/14NWNW

Location ID: 335686

Date: 10/24/2024



Photo # 8050 Location



Photo # 8085 SE corner of location

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/14NWNW

Location ID: 335686

Date: 10/24/2024



Photo # 8086 NE corner of location



Photo # 8087 NW corner of location

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/14NWNW

Location ID: 335686

Date: 10/24/2024



Photo # 8044 Debris



Photo # 8045 Debris

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/14NWNW

Location ID: 335686

Date: 10/24/2024



Photo # 8073 Debris



Photo # 8074 Debris

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/14NWNW

Location ID: 335686

Date: 10/24/2024



Photo # 8083 Debris



Photo # 8075 Wildlife hazard

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/14NWNW

Location ID: 335686

Date: 10/24/2024



Photo # 8076 Wildlife hazard



Photo # 8077 Wildlife hazard

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/14NWNW

Location ID: 335686

Date: 10/24/2024



Photo # 8080 Wildlife hazard



Photo # 8060 Open ended load line

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/14NWNW

Location ID: 335686

Date: 10/24/2024



Photo # 8061 Open ended load line



Photo # 8063 Open ended load line

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/14NWNW

Location ID: 335686

Date: 10/24/2024



Photo # 8064 Open ended load line



Photo # 8065 Open ended load line

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/14NWNW

Location ID: 335686

Date: 10/24/2024



Photo # 8066 Open ended load line



Photo # 8069 Open ended load line