

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/15/2024

Submitted Date:

10/21/2024

Document Number:

707801175

FIELD INSPECTION FORM

 Loc ID 335857 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 ECMC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202
Findings:

- 12 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290948	WELL	PR	12/01/2021	GW	045-14230	697-13C 25	PR
290994	WELL	PR	10/01/2022	GW	045-14248	697-13C 12	PR
290997	WELL	SI	07/01/2024	GW	045-14251	697-13C 27	SI
290998	WELL	PR	09/01/2020	GW	045-14252	697-13C 14	PR
291000	WELL	PR	11/12/2008	GW	045-14254	697-13C 21	PR
292006	WELL	PR	10/31/2008	GW	045-14563	697-13C 23	PR
292007	WELL	PR	09/01/2021	GW	045-14562	697-13C 16	PR

General Comment:**ECMC Inspection Report Summary**

On Tuesday 10/15/2024, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus Marathon 13C, at Location # 335857 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Random debris
2. Missing cap/plug on tank
3. Well signage lacking information
4. Lack of battery signage

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Well signage lacking information(API)		
Corrective Action:	Provide proper signage	Date:	12/20/2024
Type	BATTERY		
Comment:	Lack of battery signage		
Corrective Action:	Provide proper signage	Date:	12/20/2024

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	11/07/2024

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:


Multiple Spills and Releases?

Equipment:

Type:				corrective date
Horizontal Heated Separator	# 8			
Comment:				
Corrective Action:		Date:		
Bird Protectors	# 4			
Comment:				
Corrective Action:		Date:		
Bradenhead	# 7			
Comment:				
Corrective Action:		Date:		
Plunger Lift	# 7			
Comment:				
Corrective Action:		Date:		

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	400 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities			
Facility ID: 290948	Type: WELL	API Number: 045-14230	Status: PR Insp. Status: PR
Producing Well			
Comment: Producing			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: 290994	Type: WELL	API Number: 045-14248	Status: PR Insp. Status: PR
Producing Well			
Comment: Producing			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: 290997	Type: WELL	API Number: 045-14251	Status: SI Insp. Status: SI
Idle Well			
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned	Reminder: _____		
Comment: Loast produced 7/2024			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: 290998	Type: WELL	API Number: 045-14252	Status: PR Insp. Status: PR
Producing Well			
Comment: Producing			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: 291000	Type: WELL	API Number: 045-14254	Status: PR Insp. Status: PR
Producing Well			
Comment: Producing			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: 292006	Type: WELL	API Number: 045-14563	Status: PR Insp. Status: PR
Producing Well			
Comment: Producing			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: 292007	Type: WELL	API Number: 045-14562	Status: PR Insp. Status: PR
Producing Well			
Comment: Producing			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			



Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Culverts				
		Ditches				
Gravel						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403964893	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6754890
707801183	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6754857