

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/15/2024

Submitted Date:

10/21/2024

Document Number:

707801176

FIELD INSPECTION FORM

Loc ID 335463 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 ECMC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202

Findings:
14 Number of Comments
4 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286500	WELL	PR	05/01/2009	GW	045-12686	PUCKETT 31A-24D	PR
286516	WELL	SI	06/01/2024	GW	045-12693	PUCKETT 42A-24D	SI
286517	WELL	PR	05/01/2009	GW	045-12692	PUCKETT 41C-24D	PR
286519	WELL	PR	06/01/2009	GW	045-12691	PUCKETT 41B-24D	PR
286522	WELL	PR	11/27/2008	GW	045-12690	PUCKETT 41A-24D	PR
286523	WELL	SI	08/01/2022	GW	045-12687	PUCKETT 31B-24D	PA
286530	WELL	PR	01/01/2011	GW	045-12689	PUCKETT 31C-24D	PR
290865	WELL	PR	04/01/2023	GW	045-14209	PUCKETT 41D-24D	PR
290866	WELL	SI	08/01/2022	GW	045-14208	PUCKETT 31D-24D	PA

General Comment:

ECMC Inspection Report Summary
 On Tuesday 10/15/2024, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus Pucket 697 mesa 6, at Location # 335463 in Garfield county Colorado.
 Any Corrective Actions from previous Inspections that have not been addressed are still applicable.
 While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:
 1. Open holes 1 next to separator is fenced but gate is open, 1 hole has no fencing.
 2. Open ended piping for thawing out dump lines on tanks and separators with exhaust from trucks.
 3. Well signage lacking information and some are on the ground
 4. Lack of battery signage
 Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lack of battery signage		
Corrective Action:	Provide proper signage	Date:	12/20/2024
Type	WELLHEAD		
Comment:	Well signage lacking information(API) and some are on the ground		
Corrective Action:	Provide proper signage	Date:	12/20/2024
Emergency Contact Number:			
Comment:	911/970-285-2615		
Corrective Action:		Date:	
Good Housekeeping:			
Type	OTHER		
Comment:	Open ended piping for thawing out dump lines on tanks and separators with exhaust from trucks.		
Corrective Action:	Eliminate possibility of wildlife to enter open lines for thawing out dump lines with exhaust from trucks.	Date:	11/07/2024
Type	OTHER		
Comment:	Open holes 1 next to separator is fenced but gate is open, 1 hole has no fencing.		
Corrective Action:	Eliminate possibility of wildlife or personnel from falling into open holes. Operators are responsible for ensuring that operations are conducted with due regard for the safety of employees, for the preservation and conservation of property, and for protecting and minimizing adverse impacts to public health, safety, welfare, the environment, and wildlife resources.	Date:	10/22/2024
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Ancillary equipment	# 2		corrective date
Comment:	Chemical tanks 1 in a plastic containment and 1 in a metal containment		
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 7		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	400 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities			
Facility ID: 286500	Type: WELL	API Number: 045-12686	Status: PR Insp. Status: PR
Producing Well			
Comment: Producing			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: 286516	Type: WELL	API Number: 045-12693	Status: SI Insp. Status: SI
Idle Well			
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____			
Comment: Last produced 6/2024			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: 286517	Type: WELL	API Number: 045-12692	Status: PR Insp. Status: PR
Producing Well			
Comment: Producing			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: 286519	Type: WELL	API Number: 045-12691	Status: PR Insp. Status: PR
Producing Well			
Comment: Producing			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: 286522	Type: WELL	API Number: 045-12690	Status: PR Insp. Status: PR
Producing Well			
Comment: Producing			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: 286523	Type: WELL	API Number: 045-12687	Status: SI Insp. Status: PA
Producing Well			
Comment: Producing			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: 286530	Type: WELL	API Number: 045-12689	Status: PR Insp. Status: PR
Producing Well			
Comment: Producing			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: 290865	Type: WELL	API Number: 045-14209	Status: PR Insp. Status: PR
Producing Well			
Comment: Producing			

Corrective Action:		Date:	
--------------------	--	-------	--

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 290866 Type: WELL API Number: 045-14208 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
		Ditches				
Berms						
		Culverts				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403964896	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6754891
707801184	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6754858