


FORM 6 Rev 11/20	State of Colorado Energy & Carbon Management Commission				DE	ET	OE	ES																						
	1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109				Replug By Other Operator																									
WELL ABANDONMENT REPORT					Document Number: 403964842																									
<p>This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.</p>					Date Received:																									
ECMC Operator Number: 10651					Contact Name: Alex Waner																									
Name of Operator: VERDAD RESOURCES LLC					Phone: (303) 2049636																									
Address: 1125 17TH STREET SUITE 550					Fax:																									
City: DENVER State: CO Zip: 80202					Email: awaner@verdadresources.com																									
For "Intent" 24 hour notice required, Name: Petrie, Erica Tel: (303) 726-3822																														
ECMC contact: Email: erica.petrie@state.co.us																														
Type of Well Abandonment Report: <input checked="" type="checkbox"/> Notice of Intent to Abandon <input type="checkbox"/> Subsequent Report of Abandonment																														
API Number 05-123-05585-00					Well Number: 1																									
Well Name: H H DUELL																														
Location: QtrQtr: SESW Section: 1 Township: 8N Range: 61W Meridian: 6																														
County: WELD Federal, Indian or State Lease Number:																														
Field Name: WILDCAT Field Number: 99999																														
Only Complete the Following Background Information for Intent to Abandon																														
Latitude: 40.684846 Longitude: -104.154310																														
GPS Data: GPS Quality Value: 1.1 Type of GPS Quality Value: PDOP Date of Measurement: 10/11/2017																														
Reason for Abandonment: <input type="checkbox"/> Dry <input type="checkbox"/> Production Sub-economic <input type="checkbox"/> Mechanical Problems																														
<input checked="" type="checkbox"/> Other Re-entry for offset frac																														
Casing to be pulled: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Estimated Depth:																														
Fish in Hole: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, explain details below																														
Wellbore has Uncemented Casing leaks: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, explain details below																														
Details:																														
Current and Previously Abandoned Zones																														
<table><thead><tr><th>Formation</th><th>Perf. Top</th><th>Perf. Btm</th><th>Abandoned Date</th><th>Method of Isolation</th><th>Plug Depth</th></tr></thead><tbody><tr><td></td><td></td><td></td><td></td><td></td><td></td></tr></tbody></table>									Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth																
Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth																									
Total: 0 zone(s)																														
Casing History																														
<table><thead><tr><th>Casing Type</th><th>Size of Hole</th><th>Size of Casing</th><th>Grade</th><th>Wt/Ft</th><th>Csg/Liner Top</th><th>Setting Depth</th><th>Sacks Cmt</th><th>Cmt Btm</th><th>Cmt Top</th><th>Status</th></tr></thead><tbody><tr><td>SURF</td><td>12+1/4</td><td>10+3/4</td><td>J55</td><td>14.5</td><td>0</td><td>320</td><td>200</td><td>320</td><td>0</td><td>VISU</td></tr></tbody></table>									Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status	SURF	12+1/4	10+3/4	J55	14.5	0	320	200	320	0	VISU
Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status																				
SURF	12+1/4	10+3/4	J55	14.5	0	320	200	320	0	VISU																				

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set	70	sks cmt from	6406	ft. to	6206	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input type="checkbox"/>
Set	70	sks cmt from	3634	ft. to	3334	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input type="checkbox"/>
Set	105	sks cmt from	1930	ft. to	1630	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input checked="" type="checkbox"/>
Set	105	sks cmt from	652	ft. to	352	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input checked="" type="checkbox"/>
Set	_____	sks cmt from	_____	ft. to	_____	ft.	Plug Type:	_____	Plug Tagged:	<input type="checkbox"/>

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 175 sacks half in. half out surface casing from 350 ft. to 0 ft. Plug Tagged: ☒

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing

Surface Plug Setting Date: _____ Cut and Cap Date: _____ Number of Days from Setting Surface Plug to Capping or Sealing the Well: _____

*Wireline Contractor: _____

*Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____

Print Name: Alex Waner

Title: Operations Engineer

Date: _____

Email: awaner@verdadresources.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: _____

Date: _____

CONDITIONS OF APPROVAL, IF ANY LIST

Expiration Date: _____

COA Type

Description

0 COA	
-------	--

ATTACHMENT LIST

<u>Att Doc Num</u>	<u>Name</u>
403964851	WELLBORE DIAGRAM
403964852	WELLBORE DIAGRAM
403964854	LOCATION PHOTO
403964856	PROPOSED PLUGGING PROCEDURE
403972733	SURFACE OWNER CONSENT

Total Attach: 5 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)