

# Final Reclamation and Stormwater Inspection

Date: 10/25/2024

Operator: BONANZA CREEK ENERGY OPERATING  
COMPANY - 8960

Location ID: 305141

Inspection Document #: 708201748

Weld County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Pronghorn 11-17  
Location ID: 305141



**Photo 1.** Facing south along the start of the access road. It does not appear that the access road has been recontoured/graded to reflect the adjacent topography.

Inspection Photos  
Location Name: Pronghorn 11-17  
Location ID: 305141



**Photo 2.** Continued from Photo 1. Red dotted line illustrates the approximate contour of the former access road.

Inspection Photos  
Location Name: Pronghorn 11-17  
Location ID: 305141



**Photo 3.** Facing north along the access road near the former location. The access road is “trough” shaped and will require additional reclamation activities to restore to the original grade.

Inspection Photos  
Location Name: Pronghorn 11-17  
Location ID: 305141



**Photo 4.** The former well location has evidence of road base material and non-uniform vegetation cover.

Inspection Photos  
Location Name: Pronghorn 11-17  
Location ID: 305141



**Photo 5.** The southern reclaimed area (former tank battery) appears to be progressing towards reclamation standards with desirable vegetation observed.

Inspection Photos  
Location Name: Pronghorn 11-17  
Location ID: 305141



**Photo 6.** Facing east from the western portion of the the former location. Reclaimed portions appear to be progressing towards vegetative standards with desirable vegetation observed.

Inspection Photos  
Location Name: Pronghorn 11-17  
Location ID: 305141



**Photo 7.** Facing west from the eastern portion of the the former location. Reclaimed portions appear to be progressing towards vegetative standards with desirable vegetation observed.

Inspection Photos  
Location Name: Pronghorn 11-17  
Location ID: 305141



**Photo 8.** Facing south from the northern portion of the the former location. Reclaimed portions appear to be progressing towards vegetative standards with desirable vegetation observed. (Red arrow indicates former well location).