

Interim Reclamation and Stormwater Inspection

Date: 10/23/24

Operator: Verdad Resources LLC - 10651

Location ID: 483467

Inspection Document #: 713901130

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Kiwi 2920
Location ID: 483467



Photo 1. The photo was taken at the well location facing North. The photo illustrates the wellhead cells are missing wildlife protection.



Photo 2. The photo was taken at the well location facing North. The photo illustrates two wellhead cells are partially full of liquid.

Inspection Photos
Location Name: Kiwi 2920
Location ID: 483467



Photo 3. The photo was taken at the well location facing East. The photo illustrates the topsoil stockpile is bare of vegetation.

Photo 4. The photo was taken at the well location facing Southeast. The photo illustrates the East side of the location.

Inspection Photos
Location Name: Kiwi 2920
Location ID: 483467



Photo 5. The photo was taken at the well location facing North. The photo illustrates soil staining around the skid.



Photo 6. The photo was taken at the well location facing North. The photo illustrates free fluids within the secondary containment.

Inspection Photos
Location Name: Kiwi 2920
Location ID: 483467



Photo 7. The photo was taken at the well location facing Northeast. The photo illustrates there is no wildlife screen on the secondary containment.



Photo 8. The photo was taken at the well location facing Northeast. The photo illustrates soil staining around production equipment.

Inspection Photos
Location Name: Kiwi 2920
Location ID: 483467



Photo 9. The photo was taken at the well location facing West. The photo illustrates free fluids within the secondary containment.



Photo 10. The photo was taken at the well location facing Southwest. The photo illustrates the stabilized stormwater outlet for the retention area.

Inspection Photos
Location Name: Kiwi 2920
Location ID: 483467



Photo 11. The photo was taken at the well location facing Southwest. The photo illustrates steep slopes along the pad edge have limited vegetation and stormwater controls.