

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/24/2024

Submitted Date:

10/28/2024

Document Number:

707603292**FIELD INSPECTION FORM**Loc ID 332482 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273485	WELL	PR	11/30/2011	OW	123-22359	LAWLEY 33-4	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL** inspection.
 Well(s): 1: Plugged & Abandoned | PA.
 Battery: Inactive | Shut-down.
 Inactive Battery SE corner GPS coordinates: 40.512875 / -104.548289

Inactive Centralized Battery formerly served 3 Location IDs
 (332483, 332482, 305085).
 (Well(s): 3: Plugged & Abandoned | PA).

Inactive Centralized Battery formerly served 1 Tank Battery Facility ID
 (Pending).

Reference (Associated Well(s), Battery Inspections):
 A.) Field Inspection Report doc. #707603290 and/or Location ID #332483
 for PA Well(s) info.
 B.) Field Inspection Report doc. #707603292 and/or Location ID #332482
 for PA Well(s) info.
 C.) Field Inspection Report doc. #707603294 and/or Location ID #305085
 for PA Well(s) info.
 D.) Field Inspection Report doc. #707603296 and/or Location ID #332483
 for Inactive Battery / Facility, Equipment info.

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective ActionL				Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Iron panel.			
Corrective Action:				Date:
Equipment:				
Type: Plunger Lift	# 0			corrective date
Comment:	Plugged & Abandoned PA. Equipment removed.			
Corrective Action:				Date:
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	273485	Type:	WELL	API Number:	123-22359	Status:	PR	Insp. Status:	PA
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On WED 10/23/2024 at approximately 13:21 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: PDC ENERGY INC Location Name: LAWLEY-66N64W/4NWSE Location ID: 332482 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Inactive Shut-down. Inactive Battery SE corner GPS coordinates: 40.512875 / -104.548289</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Form 42 Notice of PA Ops, Start: 2024-09-25. Approved. Form 42 Notice of MIRU, Start: 2024-09-25. Approved. Form 17 Brhd. test on file. Date: 2024-09-25. Approved. Chevron records cement-surface plug date: 09-26-2024. Well is NOT cut/capped. Red PTA tag posted at well. Plugged & Abandoned PA well GPS coordinates: 40.512830 / -104.552030</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	10/28/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603293	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6764172