

# Inspection Photos

ID: 312120

Operator: XTO ENERGY INC

Inspection Date: 10/28/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing east along the access road.



## Inspection Photos



**Photo 2.** Facing southeast. The location has been recontoured and reclaimed. Soils have been tracked and lightly hydromulched.



## Inspection Photos



**Photo 3.** Facing east at the north side of the location.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID:312120 | Date: 10/28/2024

## Inspection Photos



**Photo 4.** Facing east at the center of the location. A berm was installed with rock dams.



## Inspection Photos



**Photo 5.** This drainage was stabilized with rock rip/rap for stormwater run-on..



## Inspection Photos



**Photo 6.** Facing toward the east side of the location. This rip/rap outlet appears to have too much rip/rap and may affect drainage as it appears to be slightly higher gradient.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID:312120 | Date: 10/28/2024

## Inspection Photos



**Photo 7.** This electric utility line needs to be removed by coordinating removal with utility company.



Inspection Photos



**Photo 8.** Facing back west at the reclaimed location..

