

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/29/2024

Submitted Date:

10/29/2024

Document Number:

716201122

FIELD INSPECTION FORM

Loc ID 306674 Inspector Name: Carlile, Craig On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------|---------------------------------|
| , Oxy | | ECMCInspections@Oxy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 290478 | WELL | SI | 05/01/2023 | OW | 123-25101 | CANEPA 6-13 | PA |

General Comment:

Follow Up Inspection. Corrective associated with previous inspection have been accomplished.
Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect.

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------|--|-------|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|--|
| Comment: | <input style="width: 95%;" type="text"/> | | |
| Corrective Action: | <input style="width: 95%;" type="text"/> | Date: | <input style="width: 80%;" type="text"/> |

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|----------|--|-------|
| Type | WELLHEAD | | |
| Comment: | Pipe | | |
| Corrective Action: | | | Date: |

Equipment:

| | | | | |
|--------------------|-----|--|-------|--|
| | | | | corrective date |
| Type: Plunger Lift | # 0 | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | <input style="width: 80%;" type="text"/> |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected Facilities

Facility ID: 290478 Type: WELL API Number: 123-25101 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

| Comment | User | Date |
|---|----------|------------|
| Follow Up Inspection. Corrective associated with previous inspection have been accomplished. Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect. | carlilec | 10/29/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 716201123 | Photo | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6764840 |