

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/29/2024

Submitted Date:

10/29/2024

Document Number:

715800223

**FIELD INSPECTION FORM**

Loc ID 318373 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	<a href="#">All Inspections</a>
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241185	WELL	PR	07/01/2024	GW	123-08973	HAZEL MCHALE 4	PR

**General Comment:**

[This is a Wellsite Audit/Inspection.](#)

**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:	Sign is lying on the ground, Stood up for photo, Install sign to comply with Rule 605.d. CA date 3-2-2024		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 95%;" type="text"/>

**Good Housekeeping:**

Type	WEEDS		
Comment:	Tall dead vegetation around the WH, PJ & ancillary equip. Comply with Rule 606. CA date 2-8-2024		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	fabricated steel pipe & angle iron		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Ancillary equip. has fabricated steel pipe and round stock.		
Corrective Action:		Date:	

**Equipment:**

Equipment	#	corrective date
Type: Bradenhead	# 1	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	electric panel, meter box and transformers	
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Prime Mover	# 1	

Comment:	Electric motor		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 241185 Type: WELL API Number: 123-08973 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 02/27/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: Plumbed to surface

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><a href="#">ECMC Inspection Report Summary</a>                      On Tuesday 10-29-2024 at approximately 1325 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Follow up to FIR Doc # 702403053.                      Operator: KP Kauffman                      Location name:                      Location ID #318373                      Well Name: Hazel McHale 4                      API # 05-123-08973                      County: Weld                      Weather: Cloudy/windy.                      Location: Dry.                      Temperature: 56*                      While there, I observed a wellsite, PR at the time of the inspection.                      During this inspection, I observed the following possible compliance issues Have not been addressed:                      606 Housekeeping: CA date 2-8-2024.                      605.d Signs: CA date 3-2-2024.                      See attached photos.                      A follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p>	revasr	10/29/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715800224	Location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6765435">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6765435</a>