

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/29/2024

Submitted Date:

10/29/2024

Document Number:

715800225

**FIELD INSPECTION FORM**

Loc ID 332999 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

12 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	<a href="#">All Inspections</a>
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242238	WELL	PR	07/01/2023	GW	123-10029	1415 CORP GAS UNIT G 1	PR

**General Comment:**

[This is a Wellsite Audit/Inspection](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate, the sign is fading and will need to be replaced in the near future.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	barbless wire		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Ancillary equipment has fabricated steel pipe		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Fabricated steel pipe		
Corrective Action:		Date:	

**Equipment:**

Type		#	corrective date
Prime Mover		# 1	
Comment:	electric motor		
Corrective Action:			Date:
Pump Jack		# 1	
Comment:			
Corrective Action:			Date:
Bradenhead		# 1	
Comment:			
Corrective Action:			Date:
Ancillary equipment		# 1	
Comment:	Electric panel, meter box and transformers		
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 242238 Type: WELL API Number: 123-10029 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR meter box, electric panel are shut off.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 02/07/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: Plumbed to surface

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">Routine Audit/Inspection</a> Any corrective actions from previous Inspections that have not been addressed are still applicable Weather: Cloudy & windy Temperature: 56* Location: Dry.	revasr	10/29/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715800226	Location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6765437">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6765437</a>