

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/29/2024

Submitted Date:

10/29/2024

Document Number:

715201147**FIELD INSPECTION FORM**Loc ID 324853 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 37230Name of Operator: HALDE OIL INCAddress: 46321 HWY 24City: BURLINGTON State: CO Zip: 80807**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Shalberg, Greg	719-688-3547	gregshalberg@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213222	WELL	SI	05/01/2024	OW	061-06584	JAGEE 1	PA

General Comment:

SE Compliance Specialist Brian Welsh conducted a P&A Inspection

Well was plugged. Operator has 30 days to remove equipment from location and begin final reclamation

Location**Lease Road:**

Type	Access		
comment:	Gravel road through farm ground		
Corrective Action	L	Date:	

Overall Good: ☒**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:	Piping, valves and misc stuff laying around		
Corrective Action:	Comply with Rule 606	Date:	11/29/2024

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: FWKO	# 1		corrective date
Comment:	FWKO on east side of oil tanks		
Corrective Action:	Remove from location to begin final reclamation process		Date: 11/29/2024

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		38.509800,-102.395170
Comment:	Fiberglass open top water tank on east side of location				
Corrective Action:	Remove from location to begin final reclamation process				Date: 12/04/2024

Paint

Condition	
Other (Content)	
Other (Capacity)	210bbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS

CRUDE OIL	2	300 BBLs	STEEL AST		38.509750,-102.395550	
Comment: 2-Crude oil tanks						
Corrective Action: Remove from location to begin final reclamation process					Date: 11/29/2024	
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
<u>Venting:</u>						
Yes/No						
Comment:						
Corrective Action:					Date:	
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities											
Facility ID:	213222	Type:	WELL	API Number:	061-06584	Status:	SI	Insp. Status:	PA		
Cement											
Cement Contractor											
Contractor Name:					HP Oilfield Services					Contractor Phone:	
Surface Casing											
Cement Volume (sx):										Circulate to Surface:	
Cement Fall Back:										Top Job, 1" Volume:	
Intermediate Casing											
Cement Volume (sxs):										Good Return During Job:	
Production Casing											
Cement Volume (sx):										Good Return During Job:	
Plugging Operations											
Depth Plugs(feet range):					4329/1350/900/366					Cement Volume (sx):	192 sxs
Good Return During Job:					YES					Cement Type:	Class A
Comment:					HALDE WATER, HP OILFIELD SERVICES, CODELL WELL SERVICES. INSPECTOR WITNESSED - MIRU CODELL, RIH W/CICR TO 900'. MIRU HP, PUMP 50SXS THRU W/12SXS ON TOP. MIRU CODELL, POOH W/TBG. MIRU HP, BREAK CIRC W/14BBLS, PUMP 130SXS W/CMT TO SFC.						
Corrective Action:										Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12											

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT