

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/29/2024

Submitted Date:

10/30/2024

Document Number:

717000119

FIELD INSPECTION FORMLoc ID 440718 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	ALL INSPECTIONS
, PDC		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443366	WELL	PR	11/01/2017	OW	001-09858	Schaefer 2536-1-4HC	PR
443368	WELL	PR	01/01/2019	OW	001-09860	Schaefer 2413-3-15HN	PR
443374	WELL	PR	04/01/2019	OW	001-09866	Schaefer LD 13-031HN	PR
458703	WELL	PR	04/27/2019	OW	001-10253	Schaefer LD 13-033HN	PR
458704	WELL	PR	10/01/2022	OW	001-10254	Schaefer LD 13-032HC	PR
458705	WELL	PR	04/27/2019	OW	001-10255	Schaefer LD 13-032HN	PR
469470	SPILL OR RELEASE	CL	01/10/2020		-	Schaefer LD 13-032HC	UN

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Emission Control Device

5

Comment:

Corrective Action:

Date:

Type: Bird Protectors

13

Comment:

Corrective Action:

Date:

Type: Bradenhead

7

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

4

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Type: Vertical Separator

3

Comment:

Corrective Action:

Date:

Type: Plunger Lift

6

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	OTHER	FIBERGLASS AST		,

Comment:							
Corrective Action:						Date:	

Paint

Condition	Adequate						
Other (Content)							
Other (Capacity)		533bbbls					
Other (Type)							

Berms

Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance	
Metal	Adequate	Walls Sufficent		Base Sufficent		Adequate	
Comment:							
Corrective Action:						Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	6	OTHER	STEEL AST		39.944862,-104.834923		
Comment:							
Corrective Action:						Date:	

Paint

Condition	Adequate						
Other (Content)							
Other (Capacity)		533bbbls					
Other (Type)							

Berms

Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance	
Metal	Adequate	Walls Sufficent		Base Sufficent		Adequate	
Comment:							
Corrective Action:						Date:	

Wells Served By Facilities Above

AirsID

API Number	API Number	AirsID
001-09860		
001-10254		
001-10253		
001-10255		
001-09858		
001-09866		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 443366 Type: WELL API Number: 001-09858 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 443368 Type: WELL API Number: 001-09860 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 443374 Type: WELL API Number: 001-09866 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 458703 Type: WELL API Number: 001-10253 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 458704 Type: WELL API Number: 001-10254 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 458705 Type: WELL API Number: 001-10255 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 469470 Type: SPILL OR API Number: - Status: CL Insp. Status: UN

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: Annual Brhd Completed?

Last Brhd Test Results Initial Surf Csg Pressure: Fluid Type:

End Surf Csg Pressure:

Comment: Appeared to be plumbed to the surface

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Routine inspection	finkenbc	10/30/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717000120	Inspection photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6767161