

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad

Location #: 335176

Oct 30, 2024 at 10:55:44 AM



Photo # 8149 From entrance to location

Oct 30, 2024 at 10:57:04 AM



Photo # 8150 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad

Location #: 335176



**Photo # 8151 Possible wellhead leak/gas bubbling up through water around wellhead (FEDERAL RMV 63-19 well)**



**Photo # 8152 Possible wellhead leak/gas bubbling up through water around wellhead (FEDERAL RMV 63-19 well)**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad

Location #: 335176



**Photo # 8153 Possible wellhead leak/gas bubbling up through water around wellhead (FEDERAL RMV 63-19 well)**



**Photo # 8154 Possible wellhead leak/gas bubbling up through water around wellhead (FEDERAL RMV 63-19 well)**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad

Location #: 335176



**Photo # 8155 Possible wellhead leak/gas bubbling up through water around wellhead (FEDERAL RMV 63-19 well)**

**Photo # 8156 Possible wellhead leak/gas bubbling up through water around wellhead (FEDERAL RMV 63-19 well)**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad

Location #: 335176



**Photo # 8157 Possible wellhead leak/gas bubbling up through water around wellhead (FEDERAL RMV 63-19 well)**



**Photo # 8158 Possible wellhead leak/gas bubbling up through water around wellhead (FEDERAL RMV 63-19 well)**