

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/24/2024

Submitted Date:

10/24/2024

Document Number:

713301214**FIELD INSPECTION FORM**Loc ID 319203 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**21 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK	303-825-4822	cogcc@kpk.com	<a href="#">all inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418033	WELL	PR	12/01/2017	OW	123-31819	SRC Pratt 34-29D	PR
418034	WELL	PR	12/01/2017	GW	123-31820	SRC Pratt 43-29D	PR
418035	WELL	PR	11/01/2022	GW	123-31821	SRC Pratt 29TD	PR
418036	WELL	PR	11/01/2022	GW	123-31822	SRC Pratt 29XD	PR
421226	WELL	PR	06/01/2024	OW	123-32857	SRC Pratt 29PD	PR
421239	WELL	PR	06/01/2024	OW	123-32862	SRC Pratt 33-29D	PR

**General Comment:**[well site and facility inspection](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	good		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	good		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	good, six wells		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	DEAD vegetation, complete facility		
Corrective Action:	Comply with Rule 606	Date:	10/31/2024
Type	UNUSED EQUIPMENT		
Comment:	custom fence panels,		
Corrective Action:		Date:	

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	custom metal panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	custom metal panels		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	custom metal panels		
Corrective Action:		Date:	
Type	TANK BATTERY		

Comment: <a href="#">custom metal panels</a>			
Corrective Action:		Date:	

**Equipment:**

Type: Ancillary equipment	# 13		corrective date
Comment: <a href="#">automation panels</a>			
Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 6		
Comment: <a href="#">piped to surface</a>			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment: <a href="#">shared with crude tanks</a>					
Corrective Action:		Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS

CRUDE OIL	4	300 BBLs	STEEL AST			
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					
		Date:			

**Wells Served By Facilities Above**

API Number
123-31820
123-31862
123-31821
123-31819
123-31822
123-31857

**AirsID**

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 418033 Type: WELL API Number: 123-31819 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: Valves appeared to be closed at time of inspectionCorrective Action:  Date: **BradenHead**Date of Last Brhd Test: 01/03/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action:  Date: 

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 418034 Type: WELL API Number: 123-31820 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: Valves appeared to be closed at time of inspectionCorrective Action:  Date: **BradenHead**Date of Last Brhd Test: 04/26/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action:  Date: 

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 418035 Type: WELL API Number: 123-31821 Status: PR Insp. Status: PR**Producing Well**Comment: PR, Valves appeared to be open at time of inspectionCorrective Action:  Date: **BradenHead**Date of Last Brhd Test: 06/25/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action:  Date: 

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 418036 Type: WELL API Number: 123-31822 Status: PR Insp. Status: PR

**Producing Well**Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 07/17/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 421226 Type: WELL API Number: 123-32857 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: Valves appeared to be closed at time of inspection

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 04/26/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 421239 Type: WELL API Number: 123-32862 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: Valves appeared to be closed at time of inspection

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 09/09/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>Inspector Michael Kester, conducted an on-site follow up inspection per doc 713301017 ,volume &amp; placards on produced water tank have been corrected Location: SRC Pratt 34-29D Operator: KPK API#: 123-31819 County: Weld While there, I observed well site and production facility During this inspection the following possible compliance issues were observed:</p> <p>Debris DEAD vegetation, whole site, Comply with Rule 606, corrective action date 10-31 -2024 ALL Photos</p> <p>Weather conditions: over cast and dry</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p> <p>This inspection does not nullify any orders or NOAV from the ECMC This is a continuing education inspection</p>	kesterm	10/24/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403969512	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6759555">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6759555</a>
713301215	site pic	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6759542">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6759542</a>