

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/28/2024

Submitted Date:

10/28/2024

Document Number:

714201811

**FIELD INSPECTION FORM**

Loc ID 311325 Inspector Name: Santistevan, Brittani On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 8 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name  | Phone          | Email            | Comment                          |
|---------------|----------------|------------------|----------------------------------|
| ,             |                | cogcc@kpk.com    | <a href="#">All Inspections</a>  |
| Tibbs, Dan    | 970-539-0664   | Dtibbs@kpk.com   |                                  |
| Watzman, Ross | (303) 825-4822 | rwatzman@kpk.com | <a href="#">all inspections.</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 241895      | WELL | SI     | 06/01/2024  | OW         | 123-09686 | MUSICK-MCCLINTOCK 3 | SI          |

**General Comment:**

[This is an audit of MUSICK-MCCLINTOCK #3 scout card and related documents followed by a field inspection.](#)

**Location**

Overall Good:

**Signs/Marker:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | BATTERY   |       |            |
| Comment:           | No sign displayed. See attached photo.                            |       |            |
| Corrective Action: | Comply with Rule 605.e.   | Date: | 11/28/2024 |
| Type               | TANK LABELS/PLACARDS  |       |            |
| Comment:           | One tank does not display contents/capacity. See attached photos. |       |            |
| Corrective Action: | Comply with Rule 605.h.   | Date: | 11/28/2024 |

**Emergency Contact Number:**

|                    |                      |  |                            |
|--------------------|----------------------|--|----------------------------|
| Comment:           | <input type="text"/> |  |                            |
| Corrective Action: | <input type="text"/> |  | Date: <input type="text"/> |

**Good Housekeeping:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | WEEDS   |       |            |
| Comment:           | overgrown vegetation on various areas of location. See attached photos. |       |            |
| Corrective Action: | Comply with Rule 606.   | Date: | 11/28/2024 |

Overall Good:

**Spills:**

| Type | Area | Volume |  |
|------|------|--------|--|
|      |      |        |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

| Type                        | #                    |  |       | corrective date |
|-----------------------------|----------------------|--|-------|-----------------|
| Horizontal Heated Separator | # 1                  |  |       |                 |
| Comment:                    | <input type="text"/> |  |       |                 |
| Corrective Action:          |                      |  | Date: |                 |
| Bird Protectors             | # 1                  |  |       |                 |
| Comment:                    | <input type="text"/> |  |       |                 |
| Corrective Action:          |                      |  | Date: |                 |

**Tanks and Berms:**

| Contents           | #                    | Capacity | Type           | Tank ID | SE GPS |
|--------------------|----------------------|----------|----------------|---------|--------|
| PRODUCED WATER     | 1                    | OTHER    | PBV FIBERGLASS |         |        |
| Comment:           | <input type="text"/> |          |                |         |        |
| Corrective Action: |                      |          |                | Date:   |        |

**Paint**

|                  |                      |  |
|------------------|----------------------|--|
| Condition        | Adequate             |  |
| Other (Content)  | <input type="text"/> |  |
| Other (Capacity) | 50 BBLs              |  |
| Other (Type)     | <input type="text"/> |  |

| <u>Berms</u>  |          |                     |                     |             |        |  |
|---|----------|---------------------|---------------------|-------------|--------|--|
| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |        |  |
|   |          |                     |                     |             |        |  |
| Comment: <a href="#">Shares contianment with other tanks.</a> |          |                     |                     |             |        |  |
| Corrective Action:  |          |                     |                     | Date:       |        |  |
| Contents  | #        | Capacity            | Type                | Tank ID     | SE GPS |  |
| OTHER   | 1        | OTHER               | STEEL AST           |             | ,      |  |
| Comment:  |          |                     |                     |             |        |  |
| Corrective Action:  |          |                     |                     | Date:       |        |  |
| <u>Paint</u>  |          |                     |                     |             |        |  |
| Condition   | Adequate |                     |                     |             |        |  |
| Other (Content)   | UNKNOWN  |                     |                     |             |        |  |
| Other (Capacity)  | UNKNOWN  |                     |                     |             |        |  |
| Other (Type)  |          |                     |                     |             |        |  |
| <u>Berms</u>  |          |                     |                     |             |        |  |
| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |        |  |
| Earth   | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |        |  |
| Comment:  |          |                     |                     |             |        |  |
| Corrective Action:  |          |                     |                     | Date:       |        |  |
| <u>Venting:</u>   |          |                     |                     |             |        |  |
| Yes/No  | NO       |                     |                     |             |        |  |
| Comment:  |          |                     |                     |             |        |  |
| Corrective Action:  |          |                     |                     | Date:       |        |  |
| <u>Flaring:</u>   |          |                     |                     |             |        |  |
| Type  |          |                     |                     |             |        |  |
| Comment:  |          |                     |                     |             |        |  |
| Corrective Action:  |          |                     |                     | Date:       |        |  |

**Inspected Facilities**

Facility ID: 241895 Type: WELL API Number: 123-09686 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           |                 | Gravel                  |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

| Comment   | User     | Date       |
|---|----------|------------|
| <p>ECMC Inspection Report Summary<br/>                     WEATHER CONDITIONS: cloudy, dry ground.<br/>                     On Monday, October 28, 2024 at approximately 1130, I, Inspector Brittani Santistevan, conducted an on-site inspection at MUSICK-MCCLINTONK #3 (KP Kauffman Company Inc), at location ID: 311325 in WELD COUNTY, Colorado.<br/>                     While there, I observed a shut-in facility.<br/>                     During this inspection the following possible compliance issues were observed:<br/>                     1. It appears to be overgrown vegetation on various areas of location. Comply with Rule 606. (Corrective Action Date: November 28, 2024) See attached photo #3-8.<br/>                     2. It appears to be no sign displayed at the tank battery. Install sign to comply with Rule 605.e. (Corrective Action Date: November 28, 2024) See attached photo #1.<br/>                     3. It appears there is no contents/capacity displayed on one tank. Install sign to comply with Rule 605.h. (Corrective Action Date: November 28, 2024) See attached photo #2.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.<br/>                     This is a summary of inspection report.</p> | santistb | 10/28/2024 |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 714201812    | Photos      | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6767888">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6767888</a> |