

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, G. JONES-67S96W/35SESE

Location ID: 334355

Date: 10/31/2024



Location Entrance – Photo #04589



Location/Lack of Stabilization – Photo #04590



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, G. JONES-67S96W/35SESE

Location ID: 334355

Date: 10/31/2024



Location – Photo #04594



Location – Photo #04592



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, G. JONES-67S96W/35SESE

Location ID: 334355

Date: 10/31/2024



Lack of Stabilization – Photo #04591



Lack of Stabilization/Degradation – Photo #04593

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, G. JONES-67S96W/35SESE

Location ID: 334355

Date: 10/31/2024



**Insufficient Tracking BMPs – Photo #04595**