

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/28/2024

Submitted Date:

11/01/2024

Document Number:

713400436

FIELD INSPECTION FORM

Loc ID 335105 Inspector Name: Popejoy, Dusty On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 25 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
ENERGY, QB		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269452	WELL	PR	10/01/2017	GW	045-09368	PUCKETT 21C-25	PR
291408	WELL	PR	12/31/2008	GW	045-14364	PUCKETT 21D-25D	PR
291409	WELL	PR	12/31/2008	GW	045-14363	PUCKETT 21C2-25D	PR

General Comment:

[CECMC Inspection Report Summary](#)

On 10/28/2024 at approximately 12:38 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection at QB ENERGY PUCKETT-66S97W/25NENW at Location ID #335105 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

1. Housekeeping - Wildlife protection for methanol tank containment needs maintenance/netting is damaged/wildlife hazard with a CA date of 11/08/2024
2. Equipment - Separator heater open to wildlife hazard/ available for entry by wildlife with a CA date of 11/08/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Location

Lease Road:			
Type	Access		
comment:	Access		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Sign near entrance to location		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	970-285-2615/911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	Refer to photos		
Corrective Action:			Date:
Type	OTHER		
Comment:	Wildlife protection for methanol tank containment needs maintenance/netting is damaged/wildlife hazard, refer to photos		
Corrective Action:	Comply with CECMC wildlife rules		Date: 11/08/2024

Overall Good:

Spills:			
Type	Area	Volume	

In Containment:	No		
Comment:			
<input type="checkbox"/>	Multiple Spills and Releases?		

Fencing/:			
Type	SEPARATOR		
Comment:	Barbed wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe fencing		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Methanol tank/containment - pipe fencing		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Wire fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 1		
Comment:	Nitrogen tank		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Separator heater open to wildlife hazard/ available for entry by wildlife, refer to photos		
Corrective Action:	Comply with CECMC wildlife rules	Date:	11/08/2024
Type: Bradenhead	# 3		
Comment:	All Bradenhead valves are accessible		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Methanol tank		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:	4 unmarked deadman - All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor, refer to photos		
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		

Comment:	
Corrective Action:	Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	500 gal	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment: Separate containment				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		,
Comment: Telemetry on tank					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 269452 Type: WELL API Number: 045-09368 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291408 Type: WELL API Number: 045-14364 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291409 Type: WELL API Number: 045-14363 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						Light compaction
		Gravel				Sparse to none in most areas
Gravel						Sparse to none in most areas
		Ditches				
Berms						
		Compaction				Light compaction

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	279647	1433090	
	279647	1433090	

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400437	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6770343