

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Jonsson 19-08 Pad

Location ID: 335195



Photo # 7752 From entrance to location



Photo # 7753 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Jonsson 19-08 Pad

Location ID: 335195



Photo # 7754 Location



Photo # 7755 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Jonsson 19-08 Pad

Location ID: 335195



Oct 28, 2024 at 2:01:38 PM
CO



Oct 28, 2024 at 2:04:15 PM
CO

Photo # 7756 Location

Photo # 7757 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Jonsson 19-08 Pad

Location ID: 335195



Photo # 7758 Location



Photo # 7759 Rupture disc vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Jonsson 19-08 Pad

Location ID: 335195



Photo # 7760 Rupture disc vent line does not comply with CECMC pressure safety device rules